

LightWalker AT and ATS Danger Laser Controlled Area Warning Sign in English

- Instructions:
1. Print the document on white paper with a color (required) printer (suggest using a heavier / card stock paper).
 2. Save document as a PDF, for future use.
 3. Trim printout at the black border of the image and then laminate sign for use.
 5. Place the Danger Laser Controlled Area Signs in all the appropriate locations when utilizing the LightWalker AT or ATS Laser.
 6. Remove Warning Signs when the LightWalker is no longer in use.



DANGER

**VISIBLE and/or INVISIBLE LASER RADIATION
AVOID EYE OR SKIN EXPOSURE
TO DIRECT OR SCATTERED
RADIATION**



EYE PROTECTION REQUIRED

Er:YAG 2940 nm Laser
Maximum Average Power: 20 watts

Nd:YAG 1,064 nm Laser
Maximum Average Power: 15 watts

Diode 532 nm Laser Maximum Average Power: <1mW

Class 4 Laser